



TECHNICAL SERVICE BULLETIN

TSB No. 210-2418 Edition 2	Date December 2004	9-3 (9400)
Distr. all		

Oil leakage from engine

Cars affected

Saab 9-3 M99 - M03 with engine variants B205 and B235

Background

The procedure in accordance with SI 210-2418 edition 1 is discontinued, as in some cases it can cause oil consumption.

A new procedure is under development.

Saab Automobile AB Bulletins are intended for use by professional Saab technicians only, NOT a "do-it-yourselfer". They are designed to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Saab trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have the condition. See your authorized Saab Dealer for information on whether your vehicle may benefit from the information.
© 2004 Saab Automobile AB. All rights reserved.

ENG